IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re patent of:

Baumer et al.

Patent. No.: 7,373,561 B2

Issued: May 13, 2008

For: Integrated Packet Bit Error Rate

Tester for 10G SERDES

Confirmation No.: 7513

Art Unit: 2117

Examiner: Gandhi, Dipakkumar B.

Atty. Docket: 1875.4430000

Request for Certificate of Correction Under 37 C.F.R. § 1.322

Attn: Certificate of Correction Branch

Commissioner for Patents PO Box 1450 Alexandria, VA 22313-1450

Sir:

It is hereby requested that a Certificate of Correction under 37 C.F.R. § 1.322 be issued for the above-captioned United States Patent. This Certificate of Correction is being requested due to mistakes which appear in the printed patent. These mistakes were made by the U.S. Patent and Trademark Office.

Specifically, the printed patent contains the following error for which a Certificate of Correction is respectfully requested:

In column 17, line 32, "redundancy cheek" should be replaced with --redundancy check--.

Remarks

The above-noted correction does not involve such changes in the patent as would constitute new matter or would require reexamination.

A completed Form PTO/SB/44 accompanies this request, with the above-noted correction printed thereon. Accordingly, a Certificate of Correction is believed proper and issuance thereof is respectfully requested.

The Commissioner is hereby authorized to charge any fee deficiency, or credit any overpayment, to our Deposit Account No. 19-0036.

Respectfully submitted,

Sterne, Sessler, Goldstein & Fox p.l.l.c.

James J. Pohl

Attorney for Patentees Registration No. 60,724

Date: <u>April 15, 2009</u>

1100 New York Avenue, N.W. Washington, D.C. 20005-3934 (202) 371-2600

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Ì		
PATENT NO. :	7,373,561 B2	Page <u>1</u> of <u>1</u>
APPLICATION NO.:	10/681,244	
ISSUE DATE :	May 13, 2008	
INVENTOR(S) :	Howard A. Baumer et al.	
It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:		
In column 17, line 32, "redundancy cheek" should be replaced withredundancy check		

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Sterne, Kessler, Goldstein & Fox P.L.L.C.

1100 New York Avenue, N.W.

Washington, DC 20005-3934

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.